



Work confirmation of the feed bar



Previous problems

- Cable disconnection by the curve.
- Time loss caused by attaching or detaching of connector when exchanging die.






After improvement

- Efficiency of the exchange the feed bar.
- Resolution of the disconnection trouble.
- No problems in an environment of water or the oil.

Point

Because of a kind and the placement of the gripper vary according to the press line using the feed bar, in the case of die exchange the feed bar changes as well. Because of the remote system the exchange work can be shortened.



Configuration

