

# Comparison table of BICs and B&PLUS

(1/2)

| Order code of Balluff | Part number of Balluff         | EDP No. of Balluff | Material No. of B&PLUS | Part number of B&PLUS   |
|-----------------------|--------------------------------|--------------------|------------------------|-------------------------|
| BAE00HA               | BAE SA-IC-022-PIO-P64          | 222034             | 1050628                | RL64T-344P-000          |
| BAE00HC               | BAE SA-IC-021-DNT-64           | 222035             | 1060112                | RL64EA-355DN-000        |
| BIC000W               | BIC 1I3-P2A40-M30MO2-BPX0B-050 | 179301             |                        | No replacement          |
| BIC000Y               | BIC 2I3-P2A40-M30ME2-BPX09-050 | 179302             |                        | No replacement          |
| BIC0011               | BIC 1I3-P2A40-M18MN2-BPX0B-050 | 179511             |                        | No replacement          |
| BIC0012               | BIC 2I3-P2A40-M18MF2-BPX09-050 | 179512             |                        | No replacement          |
| BIC0015               | BIC 1I2-P2A02-M18MN2-EPX07-050 | 180592             | 1021023A               | RPEA 1803P-PU-05        |
| BIC0016               | BIC 1I2-P2A02-M18MN2-EPX07-020 | 180593             | 1031103A               | RPEA 1803P-PU-02        |
| BIC0019               | BIC 1I2-P2A03-M30MO2-EVX07-100 | 180596             |                        | No replacement          |
| BIC001A               | BIC 1I2-P2A03-M30MO2-EPX07-050 | 180597             | 1040108A               | RPEA 3005P-PU-05        |
| BIC001C               | BIC 1I2-P2A03-M30MO2-APX07-050 | 180598             |                        | No replacement          |
| BIC001H               | BIC 1I3-P2A05-Q80KA-GVX0C-100  | 180601             |                        | No replacement          |
| BIC001J               | BIC 1I3-P2A05-Q80KA-GPX0C-050  | 180604             | 1140502                | RPEA 8015P-PU-05        |
| BIC001K               | BIC 1I3-N2A05-Q80KA-GPX0C-030  | 180606             | 1130608                | RPEA 8015N-PU-03        |
| BIC001L               | BIC 1I3-N2A05-Q80KA-GPX0C-020  | 180607             | 1110908                | RPEA 8015N-PU-02        |
| BIC001N               | BIC 2I2-P2A02-M18MF2-EPX07-050 | 180631             | 1031149A               | RPTA 1803-PU-05         |
| BIC001P               | BIC 2I2-P2A02-M18MF2-EPX07-010 | 180632             | 1031025A               | RPTA 1803-PU-01         |
| BIC001T               | BIC 2I2-P2A03-M30MF2-EPX07-050 | 180634             | 1031114A               | RPTA 3005-PU-05         |
| BIC001U               | BIC 2I2-P2A03-M30MF2-APX07-050 | 180635             |                        | No replacement          |
| BIC001Y               | BIC 2I3-P2A05-Q80KA-GPX0C-050  | 180637             | 1140501                | RPTA 8015-PU-05         |
| BIC001Z               | BIC 2I3-P2A05-Q80KA-GPX0C-010  | 180638             | 1110907                | RPTA 8015-PU-01         |
| BIC0021               | BIC 2I3-P2A20-Q40AA-GPX0B-050  | 180647             | 1001491A               | RGPT 4008-V1220A-PU-05  |
| BIC0022               | BIC 2I3-P2A20-Q40AC-GPX0B-050  | 180648             | 1001494A               | RGPT 4008-V1220B-PU-05  |
| BIC0023               | BIC 2I3-P2A30-Q90AA-GPX0B-050  | 180649             | 1001498A               | RGPT 9012-V2430-PU-05   |
| BIC0025               | BIC 1I3-P2A15-M30MM3-BPX0B-100 | 180651             | 1050501                | RGPE 3005-V1215P-PU-10  |
| BIC0026               | BIC 1I3-P2A20-Q40AA-GPX0B-050  | 180652             | 1001476A               | RGPE 4008-V1220PA-PU-05 |
| BIC0027               | BIC 1I3-P2A20-Q40AC-GPX0B-050  | 180653             | 1001478A               | RGPE 4008-V1220PB-PU-05 |
| BIC0028               | BIC 1I3-P2A30-Q90AA-GPX0B-050  | 180655             | 1001484A               | RGPE 9012-V2430P-PU-05  |
| BIC0029               | BIC 1I0-P2A02-M18MI-BPX03-050  | 180662             | 1020716                | RPE 1804P-PU-05         |
| BIC002A               | BIC 1I0-P2A02-M18MI-BPX03-020  | 180663             | 1020711                | RPE 1804P-PU-02         |
| BIC002C               | BIC 1I0-N2A02-M18MI-BPX03-020  | 180664             | 1031076                | RPE 1804N-PU-02         |
| BIC002E               | BIC 1I0-P2A02-M30MI-BPX03-050  | 180665             | 1031099                | RPE 3008P-PU-05         |
| BIC002F               | BIC 1I0-P2A02-M30MI-BPX03-020  | 180666             | 1031082                | RPE 3008P-PU-02         |
| BIC002H               | BIC 1I0-N2A02-M30MI-BPX03-020  | 180667             | 1031098                | RPE 3008N-PU-05         |
| BIC002J               | BIC 2I0-P2A02-M18ME-BPX03-010  | 180669             | 1031017                | RPT 1804P-PU-01         |
| BIC002K               | BIC 2I0-P2A02-M18ME-BPX03-020  | 180670             | 1040120                | RPT 1804P-PU-02         |
| BIC002L               | BIC 2I0-N2A02-M18ME-BPX03-010  | 180671             | 1030911                | RPT1804N-PU-01          |
| BIC002P               | BIC 1I0-P2001-M18MI-BPX03-050  | 180679             | 1002023                | RXE 1805P-PU-05         |
| BIC002R               | BIC 1I0-P2001-M18MI-BPX03-020  | 180680             | 1031125                | RXE 1805P-PU-02         |
| BIC002T               | BIC 1I0-P2001-M12MM1-BPX03-050 | 180681             | 1002004                | RXE 1202P-PU-05         |
| BIC0039               | BIC 2B2-P2A30-Q90AQ-GPX0B-050  | 180696             | 1030104A               | RHPT8 8010P-C3-PU-05    |
| BIC003C               | BIC 1B2-P2A30-Q90AQ-GPX0B-050  | 180699             | 1030105A               | RHPE8 8010P-C3-PU-05    |
| BIC003U               | BIC 1I0-P2A02-M30MI-BPX03-100  | 180668             | 1050820                | RPE 3008P-PU-10         |
| BIC003W               | BIC 2I0-D1001-M12ME1-BPX02-050 | 180743             | 1002040                | RXT 1202-PU-05          |
| BIC003Y               | BIC 2I0-D1001-M12ME1-BPX02-010 | 180744             | 1031129                | RXT 1202-PU-01          |
| BIC003Z               | BIC 2I0-D1001-M18ME1-BPX02-050 | 180745             | 1002056                | RXT 1805-PU-05          |
| BIC0041               | BIC 2I0-R1002-M18MF2-BPX03-050 | 180747             | 1030636A               | RTT 1804-PT1B10-PU-05   |
| BIC0042               | BIC 2I0-R2002-M18MF2-BPX03-050 | 180748             | 1060508A               | RTT 1804-PT1B20-PU-05   |
| BIC0043               | BIC 2I0-V1A01-M18MI2-BPX03-050 | 181668             | 1020610A               | RNT 1803-VS10-PU-05     |
| BIC0044               | BIC 2I0-P2A05-M30MF-BPX03-030  | 181669             | 1051206                | RPT 3008P-PU-03         |
| BIC0045               | BIC 2I3-P2A15-M30MI2-BPX0B-050 | 181670             | 1001489A               | RGPT 3005-V1215-PU-05   |
| BIC0046               | BIC 1I0-V1003-M18MN2-BPX03-050 | 181671             | 1020611A               | RNE 1803A-PU-05         |
| BIC0047               | BIC 1I0-C1A02-M18MN2-BPX03-050 | 181672             | 1030637A               | RTE 1804E-PU-05         |
| BIC0048               | BIC 1I3-P2A15-M30MM3-BPX0B-050 | 181673             | 1001469                | RGPE 3005-V1215P-PU-05  |
| BIC004C               | BIC 2I0-R3002-M18MF2-BPX03-050 | 183025             | 1091103A               | RTT 1804-PT1B30-PU-05   |
| BIC004M               | BIC 915-D2-M08EE-EPX02-010     | 185627             | 1001904                | RXD 0801-PU-01          |
| BIC004N               | BIC 902-D2-M12ME-EPX02-020     | 185628             | 1031118                | RXD 1202-PU-02          |
| BIC004P               | BIC 902-D2-M12ME-EPX02-100     | 185629             | 1040210                | RXD 1202-PU-10          |
| BIC004R               | BIC 902-D2-M12ME-EVX02-150     | 185630             |                        | No replacement          |
| BIC004T               | BIC 902-D2-M12ME-EPX02-010     | 185631             | 1001912                | RXD 1202-PU-01          |
| BIC004U               | BIC 905-D2-M18ME-EVX02-150     | 185632             |                        | No replacement          |
| BIC004W               | BIC 905-D2-M18ME-EPX02-010     | 185633             | 1001924                | RXD 1805-PU-01          |
| BIC004Y               | BIC 910-D2004-M30MF-EPX02-010  | 185634             |                        | No replacement          |
| BIC004Z               | BIC 910-D2004-M30MF-EPX02-030  | 185635             |                        | No replacement          |
| BIC0050               | BIC 910-D2-M30MF-EPX02-010     | 185636             |                        | No replacement          |

| Order code of Balluff | Part number of Balluff            | EDP No. of Balluff | Material No. of B&PLUS | Part number of B&PLUS       |
|-----------------------|-----------------------------------|--------------------|------------------------|-----------------------------|
| BIC005K               | BIC 2I0-P2A02-M30TI-BPX03-030     | 219949             | 1061010                | RPT TF3008P-PU-03           |
| BIC005L               | BIC 1I0-P2A02-M30TI-BPX03-030     | 219950             | 1061014                | RPE TF3008P-PU-03           |
| BIC005M               | BIC 2I0-D2A02-M30TI-BPX03-030     | 219951             | 1031165                | RPT TF3008D-PU-03           |
| BIC005N               | BIC 1I0-N2A02-M30TI-BPX03-030     | 219952             | 1060801                | RPE TF3008N-PU-03           |
| BIC005P               | BIC 2I0-N2A02-M18TI-BPX03-050     | 219953             | 1050201                | RPT TF1804N-PU-05           |
| BIC005R               | BIC 2I0-D2A02-M18TI-BPX03-050     | 219954             | 1031163                | RPT TF1804D-PU-05           |
| BIC005T               | BIC 1I0-N2A02-M18TI-BPX03-050     | 219955             | 1031160                | RPE TF1804N-PU-05           |
| BIC005Z               | BIC 1I3-P2A30-Q90AA-GPX0B-Z04     | 219966             | 1070618A               | RGPE 9012-V2430P-SA03-PU-02 |
| BIC0060               | BIC 2I3-P2A30-Q90AA-GPX0B-Z05     | 219967             | 1070619A               | RGPT 9012-V2430-SA02-PU-01  |
| BIC0068               | BIC 2I3-D2A04-M30MO2-BPX0B-050    | 221195             | 1020502A               | RPT8-3007D-PU-05            |
| BIC0069               | BIC 1I2-N1A02-M18MN2-EPX07-050    | 221196             | 1040238A               | RPEA-1803N-PU-05            |
| BIC006A               | BIC 1I3-N1A15-M30MM3-BPX0B-050    | 221197             | 1001467                | RGPE-3005-V1215N-PU-05      |
| BIC006C               | BIC 1I4-N1A15-M30ME1-BPX0F-050    | 221198             | 1080405                | RSH16E-030N-PU-05           |
| BIC006F               | BIC 1I3-P2A04-M30MO2-BPX0B-050    | 221200             | 1030419                | RPE8-3000P-PU-05            |
| BIC006L               | BIC 2I4-Z1A15-M30ME1-BPX0F-010    | 221280             | 1060805                | RSH16T-030-PU-CP-1.0        |
| BIC006T               | BIC 1H0-X22A0-Q90AA-GPS04-020-Z14 | 222259             | 1070609                | RCH08E-211-SA01-PU-02       |
| BIC006U               | BIC 2H0-X22A0-Q90AA-GPS04-020-Z15 | 222260             | 1080609                | RCH08T-211-SA01-PU-02       |
| BIC006W               | BIC 2H0-X22A0-Q90AA-GPS04-010-Z15 | 222261             | 1070608                | RCH08T-211-SA01-PU-01       |
| BPI0068               | BPI 821030-6M-IC-THSC             | 183236             | 1001728                | RPK 2101                    |
| BPI0069               | BPI 4M4A40-2M-IC-THF7             | 183234             | 1110810                | RPK 4C01-P                  |
| BPI006A               | BPI 821020-6M-IC-THSC             | 183235             | 1001382                | RFK 3101                    |
| BPI006C               | BPI 8M4A40-2M-IC-THFC             | 183237             | 1110812                | RPK 8C01-P                  |
| BPI006E               | BPI 421030-3M-IC-THSC             | 183233             | 1001729                | RPK 2102                    |
| BPI0088               | BPI BM4A40-7K-IC-SHM4             | 220440             | 1140405                | RS16T-211P-S04              |